



Animate Parameters

 Animate Parameters




The Animate Parameters tool allows you to animate user parameters. Parameters are covered in my Intermediate level text. Parameters are defined using the Parameter tool and can be defined in a part or assembly file.

Exercise 20-8:


Animate Parameters

File: [nozzle.ipt](#) (download from publisher's website)
Estimated Time: 5 minutes

1. Open *nozzle.ipt*.



Go to **Applications**→**Inventor Studio**.

3.  Select the **Animate Parameters** tool.


4.  In the browser, expand the Parameters category.

One parameter has been defined.

Select the parameter.



Elise Moss
Excerpt from Inventor R10 Fundamentals
Available from Schroff Development Corp

5.



Set the end time to
5.0s.

Press **OK.**

6.  Select the **Go to Start** button.
7.  Select the **Play** button.
8. Save as *ex20-8.ipt*.